

## QUICK START INSTRUCTIONS

There are five different sequential polishing compounds impregnated into long bearing surface bullets. These bullets are contained in five separate compartments in this kit: numbers 1, 2, 3, 4, and 5. #1 is the most coarse, #5 is the finest.

**1** Load 10 cartridges with 10 bullets of the same numbered compound (total of 50 cartridges). Use the suggested starting load (lightest load ) with the fastest burning powder listed in your loading manual.

**2** Thoroughly clean your firearm's barrel using whichever solvent or compound you prefer (brushing is recommended). Follow label directions, but get the barrel clean.

**3** Follow the FinalFinish system process by firing each polishing compound in succession, cleaning the barrel between 10 round strings: Fire the 10 #1 bullets, clean the barrel. Fire the 10 #2 bullets, clean the barrel. Continue this sequence with the 10 #3s, then the 10 #4s, and finally the 10 #5s, always using the same fire and clean sequence each 10 rounds. Clean the bore again and you're done!